Fig. 1





Fig. 2







Fig. 3

 $A_{_{\perp}}$




 \boldsymbol{B} ...

11b

Fig. 4

A



B

	$J_1(x_1, y_1, z_1, CT_1) J_2(x_2, y_2, z_2, CT_2)$ $J_3(x_3, y_3, z_3, CT_3) \cdot \cdot \cdot \cdot \cdot \cdot \cdot \cdot$	
	• • • • • • • • • • • • • • • • • • •	
	$R'_1(x_1, y_1, z_1)$ $R'_2(x_2, y_2, z_2)$	
	$R'_3(x_3,y_3,z_3)$ · · · · · · · · · · · · · · · · · · ·	
	• • • • • • • • • • • • • • • • • • • •	
_		_

Fig. 5





Fig. 6






Fig. 7

Fig. 8




Fig. 9




Fig. 10




Fig. 11





Fig. 12






Fig. L.

mail of

Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18






Fig. 19

 \boldsymbol{A}



B



C

